

On-Site Sewage Operation and Maintenance Program Report of System Status (For Real Estate)

Mail To Information:

MICHAEL HESELTINE

40822 MOUNTAIN HIGHWAY E EATONVILLE WA 98328

Site Address:

19912 70TH AVE E SPANAWAY WA 98387

Parcel #:

3848000241

TPCHD Record Number:

SR0282458

Closing Date: 03/20/2023

Issued Date:

03/23/2023

Dwelling Type:

Single Family

(253) 677-3361

Garbage Disposal:

Ν

of Bedrooms stated by applicant:

Phone:

3

Inspection Results for:

Report of System Status (For Real Estate)

Field Inspection Completed on: 03/23/2023

Field Inspection Completed by: Napua Villarin

RSS Issued By: Napua Villarin

Telephone #: (253) 649-1865

Meets requirements for system evaluation and compliance with

Environmental Health Code, Chapter 2, Section 34.

Onsite Sewage System Information:

O&M Record #:

ON0180533

Program Element:

0622

System Classification: Standard Residential System:

Requires inspection every three years.

Approved or estimated

Wastewater Gallons Per Day:

System capacity is unknown

System Description:

Gravity

Inspector Comments:

- Septic system appears to be functioning but system was not in use at time of inspection; home/building is vacant.
- The Health Department found no record drawing document for this property during our preliminary search. We cannot verify the following:
 - 1. The location of the dispersal component (drainfield).
 - 2. The number of approved bedrooms and wastewater design flow (size of the septic system).

If you would like to request a more extensive search please submit a public records request on our website at www.tpchd.org.

Note: This is the Official Report of System Status

Valid for 12 months from Issued Date

Any person aggrieved by a decision of the health officer shall have the right to appeal such decision, in writing, within fifteen (15) days in accordance with the appeal procedures set forth in Environmental Health Code, Chapter 1.



APPLICATION FOR REPORT OF SYSTEM STATUS

ON0180533	282458		03/20/	03/20/2023	
O&M Record # (Office Use)		Application # (Office Use) Closing		Closing I	Date
Mail To Information		Site Informa	ation		RSS Validation
Michael Heseltine		Charlene R	& Dale R Larse	en	
Name		Owner Name			
40822 Mountain Highway E		3848000241			M/ED DAVAMENT
Address		Parcel #			WEB PAYMENT RECEIVED
Eatonville, WA 98328		19912 70th Ave E			03/15/2023
City/State/Zip		Site Address			
(253) 677-3361		Spanaway, WA 98387			
Phone		City/State/Z	Zip		
23 & 24 Fir Meadows		16335		16335	☐ RME Report
Lot# Subdivision	of buildings	f buildings Lot Size in Sq Ft		Last O&M: 02/22/2023	
Building Single Multi	Mobile	Food			O&M Firm:
Type: Family Family	Park	Service	Commercial	Institutional	ABC-ABLE SEPTIC SERVICE INC.
X L	Ш	Ш		Ш	
Year Built: 1971 Year Remodele	tions occured open made to to either question	during your ow	er of Bedrooms: vnership of this em during your of provide a brief deso uilt: 1971 Ph	3 property? pwnership?	how long? 1 month Yes No X Unk Yes No X Unk unk y receipts (if available).
0517 - Report of System Status (Fo	r Real Estate) -	04/13/2016	G - RSS ISSUE	ΞD	
Open Complaints CO0057617 RSS - REPORT OF			Suspended		
Microfilm Records	_				TPCHD Bar Code
		for inspecti	working days on of the e completed	;	



Report of System Status Inspection Checklist

Site Address: 19912 70th Ave E, Spanaway, WA98387

Closing Date: 03/20/20

Closing Date: 03/20/2023

Dwelling Type: Single Family

of Bedrooms: 3

O&M Record #: ON0180533

Location:

Waste Water Gallons Per Day: Unknown

Garbage Disposal: No System Type: O&M Simple Septic System/Registration

Components: Gravity

Insp	ector's Signature/Date: NV 3/23/23
	Septic system appears to be functioning at time of inspection (no surfacing sewage found).
X	Septic system appears to be functioning but system was not in use at time of inspection.
X	Exact location of the drainfield cannot be verified (no asbuilt drawing found).
	Drainfield is sized for bedrooms per Health Department records.
	Septic system was not designed to include a garbage disposal.
	Use of a garbage disposal unit is not recommended.
	This is an area of high winter water tables and/or marginal soils.
	Drainfield is located on an easement addressed as
	Part of the drainfield appears to be covered by a structure or impervious surface.
	Part of the drainfield appears to be covered by a sport court.
	Small constructed pond or fountain appears to be located in the drainfield area.
	Landscaping material placed over drainfield must allow air passage into soil.
	Green striping with lush plant growth noted in drainfield area.
	Vehicle traffic over drainfield or reserve area is not recommended.
	Drainfield is located in a pasture and may be impacted by livestock.
	Fire pit in drainfield area is not recommended.
	Health Department records indicate the water well serving this property has not received final approval.
区	RME OK
•	RSS on Hold for:
	Drainfield area was overgrown with brush / blackberries and could not be inspected; clear the drainfield are
	A field inspection revealed that there is an abandoned well on your property.
	Septic system appears to be malfunctioning at the time of the inspections:
	This application is on hold for receipt of additional inspection or other information. Check below:
	Health Department staff observed the tank or pump lid is not properly secured.
	Missing RME report
	Deficient RME report:
	Community System not current with the O&M inspection requirements.
	An unapproved septic system or component was installed on the property.